

## 2020 Annual Stream Station Visit

<b>Station</b>	Flying E Wqsh	<b>ID</b>	51707
----------------	---------------	-----------	-------

<b>Date of Field Visit</b>	May 13, 2020	<b>Photos Taken</b>	✓
----------------------------	--------------	---------------------	---

### Field Notes

<b>Initial Observations:</b>	PT / CSG buried, otherwise no changes
------------------------------	---------------------------------------

### PT Gage

<b>Housing Condition:</b>	<input checked="" type="radio"/> Buried	<input type="radio"/> Exposed	Other:		
<b>Instrument Condition:</b>	<input type="radio"/> Clean	<input type="radio"/> Clear	<input type="radio"/> Dirty	<input type="radio"/> Packed	<input type="radio"/> Other:
<b>Service Done:</b>	attempted to clean - unable to remove PT from conduit. unable to remove conduit because it is seized.				
<b>Additional Service Needed:</b>	Service / clean PT				<b>Schedule Technician:</b>
					<input checked="" type="radio"/> Y <input type="radio"/> N

### CSG Gages

	CSG	Serviced	Readings	Readings	Readings	Readings
	1	y	2.3			
	2	y				
	3					
	4					

### Staff Gages

Range	Condition	Range	Condition	Range	Condition	Range	Condition
0-10	good						

<b>Follow Up Actions</b>	rework PT, clean PT
--------------------------	---------------------

<b>Service Needed before Monsoon season?</b>	yes
--	-----

<b>Final Observations</b>	/
---------------------------	---