

2018 Annual Stream Station Visit

Station

Flying E Wash

ID

7083

Date of Field Visit

May 7, 2018

Field Notes

Initial Observations:

New setup; has been surveyed

PT Gage

Condition Found:

clean

Service Done:

None

Additional Service Needed:

CSG Gages

CSG	Serviced	Readings			
1	<i>4</i>	<i>—</i>			
2	<i>4</i>	<i>—</i>			
3					
4					

Staff Gages

Range	Condition	Range	Condition	Range	Condition	Range	Condition
<i>0-10</i>	<i>good</i>						

Follow Up Actions

None needed

Final Observations