

2019 Annual Stream Station Visit

Station	Flying E Wash	ID	7083					
Date of Field Visit	May 7, 2019	ALERT2 ID						
Field Notes								
Initial Observations:	Nothing new							
PT Gage								
Condition Found:	clean							
Service Done:	None							
Additional Service Needed:								
CSG Gages								
	CSG	Serviced	Readings					
	1	y	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">/</div> <div style="text-align: center;">/</div> </div>					
	2	y						
	3							
	4							
Staff Gages								
Range	Condition	Range	Condition	Range	Condition	Range	Condition	
0-10	good							
Follow Up Actions		None —						
Final Observations								